

TECHNICAL SERVICE BULLETIN

TB09-122R

TO: RESIDENTIAL AND MAYTAG DISTRIBUTORS
FROM: TECHNICAL SERVICE DEPARTMENT
DATE: JUNE 18, 2009
RE: EVAPORATOR COIL CORROSION

Nordyne is aware that early evaporator coil failures are an issue and testing has been performed on returned sample coils. The findings reveal that one or more factors are a primary cause: geographical location, high humidity, homes built or remodeled in approximately the past five years. Many returned samples have high levels of sulphur, a known corrosive reactant with copper.

Nordyne requires that in known corrosive environments, whether at initial installation or warranty replacement, Nordyne evaporator coils must be treated by the installing company to prevent premature failures. Nordyne recommends a coil coat dip like Bronz-Glow or an equivalent coil coat be applied please reference TB08-146R.

If you have any questions please call Nordyne Technical Service Department at 1-800-422-4328 ext. 2.

NORDYNE
Technical Service Department



Frigidaire



BROAN
HEATING AND COOLING SYSTEMS

TAPPAN

NuTone

Kelvinator
Heating and Cooling Products

PHILCO
Heating and Cooling Products

Gibson
Heating and Cooling Products

GRANDAIRE